
KOCOM

MULTIPLE OUT DOOR PANEL

DS-4M OPERATING MANUAL

Thank you very much for purchasing KOCOM multiple interphone. Please read this manual thoroughly to ensure correct usage, before operating





KOCOM CO.,LTD.

SPECIFICATION & FEATURES

POWER: DC 24V(1.2A) / POWER FROM INTERPHONE CONSUMPTION: UN LOAD; 0.3W IN LOAD; 1.0W

NO.OF WIRES: 4WIRED PARALLEL (VOICE, CALLING, POWER, GND)

RANGE: TIV 0.6 (1Km)


* 1Km(When additional DC 24V adaptor is installed)


■ COMPOSITION :

- OUT DOOR PANEL (DS-4M)
- MULTIPLE INTERPHONE (KIP-611PG/605PG) *Option
- ADAPTOR *Option
- When using DS-4M with KIP-611PG or KIP-605PG it should be No.1 in DIP switch. So KIP-611PG or KIP-605PG can not be set as No.1 in dip switch.


Name of Each Part

DS-4M






How to operate (Instruction for operating)




You can make a call pressing call button.



Pick-up the hand-set and press NO.1 button for conversation with DS-4M

Wiring Diagram



Warranty



To receive after-Sale service, have the following ready when you contact our branches

- 1. Name of the product
- 2. Model number of the product
- 3. The area of problem
- Phone number and address at which you can be contacted.

Warranty Card

PRODUCT	
MODEL	
DATE PURCHASED	
WARRANTY PERIOD	
AGENCY ADDRESS	

KOCOM Warranties the original purchaser of this product as follows.

- 1) This product is produced under strict quality control and inspection procedures.
- If this product breaks down during proper use as a result of product defect, KOCOM will repair it within one year from date of purchase free of charge.
- 3) The following cases will be subject to charge, even during warranty period:
- a. Breakdown during transport, or through careless treatment, by consumer.
- b. Breakdown cause by unauthorized repair, or system modification.
- c. Breakdown caused by natural disaster or power disorder.

This manual is based on the date as shown in the right and specifications are subject to change without notice for quality improvement.

DS-4M 06.11